



## Pyramix 6.1 MR2 Release Notes

# Installation

Please consult the Installation Guide located on the Pyramix Installation Media (CD/DVD-ROM or USB Memory card) for details of the hardware and software installation procedure and Authorization Key registration process.

To install the Mykerinos board, TURN YOUR COMPUTER OFF (shut down then switch the power off). Next plug the Mykerinos board into one of the PCI/PCI-Express bus slots on your computer and turn the power back on.

# Additional installation step for multi-board application

In order to enable multi-board operation, all Mykerinos cards in your PC have to be connected together using a special HDTDM ribbon cable. This cable has to be plugged into the multi-pin connectors located on the top edge of the I/O daughter cards. Please contact your Merging Technologies Sales Partner for information on how to order this HDTDM ribbon cable.

- To install the Pyramix Virtual Studio software insert the Pyramix Virtual Studio Installation Media the installation program should auto-start.
- To install MassCore launch the MT Security Settings, go to the MassCore page and install the MassCore RunTime (a MassCore base key is required).

# **Updates**

Please check our Web site http://www.merging.com periodically for information, patches and updates.





# Version Pyramix 6.1MR2

## **BUG FIXES** (some fixed bugs could be missing from the list)

- MT3355: Fixed. Delete track may result in a crash in some random circumstances
- MT3348: Fixed. Autopunch Record status (remote and transport window) incoherence
- MT3216: Fixed. Record: Auto-Punch internal machine does not record if track is un-arm (dubbing mode)
- MT3333: Fixed. OMF import has duplicated medias in some tracks
- MT3337: Fixed. Automation: Copy/Paste from Stereo Strip to Bus not working, automation does not follow
- MT3318: Fixed: Cinegy EDL support: If an EDL was generated by a Cinegy system, Pyramix will
  now relink to the Medias in EDL import, so they will no longer appear offline in the timeline.
- MT3313: Fixed. Media files Drag & Drop support from Explorer/iTunes to the Pyramix timeline
- MT3210: Fixed. Mixer Crash in rebuild when adding some VST plug-ins. The Waves plug-ins and Altiverb were known to cause random crashes when rebuilding the Pyramix Mixer, this issue is now resolved.
- MT3302: Fixed. Sony Track arming status is not correctly reflected in the Transport window
- MT3258: Fixed. Increase the default OASIS connection timeout to 8 seconds (improves connection to controllers with large projects)
- MT3310: Fixed. Optimization of Tab windows refresh when performing undo/redo, show/hide in Tabs.
- MT3307: Fixed. Crash when stopping a record from a controller or by chasing a TC (with display waveform while recording)
- MT3120: Fixed. Workspace: Switching between workspace in playback should no longer cause drop
- MT3284: Fixed. Reverse TimeCode chase (LTC and Sony) does not lock anymore
- MT3132: Fixed. Waveforms Display While recording will cause Pyramix hang on certain configurations due to Graphic taking all resources
- MT3297: Fixed. Timeline: Offline clips are missing Media File Name and Clip Location
- MT3168: Fixed. Record: If in enable dubbing mode the recorded clip might shift to upper tracks.
- MT1862: Fixed. Markers: create slowdown in large project, if many markers are present

## Pyramix V6 Specific Known Issues (Some issues could be missing from this list)

#### MassCore

- Hyperthreading is supported for MultiCore processors only, since Pyramix V6.1, but Merging recommends that you disable the Hyperthreading for the moment.
- MassCore is not supported on a Pentium 4 or Pentium D processor, refer to the Installation Guide for the proper supported configuration details.
- We recommend that you do not use more than 65-70% of the Core resources, to avoid intense graphic refresh burst related problems. Three safe core zones have been set. Eventually this will be optimized further.
  - 0% to 65% Green zone (best performance)
  - 65% to 75% Orange zone (moderate risk)
  - 75% to100% Red zone (performance could be at risk if major screen redraws are initiated by the user).
- If the Core indicator blinks (red), this will indicate a drop, only be concerned if the drop occurred during Playback/Mix down or record. To reset the Core drop simply do a Mouse click on the Core indicator, for more information please refer to the appropriate section in the User Manual. VST plug-ins users should consult the VST Core Load information also available in the User Manual.





- External Insert plug-ins: The same input and output cannot be used in the External Insert plug-in and the Mixer at the same time, they are exclusive to either one.
- The MADI 1 daughterboard is not supported in multi-board, neither in Mykerinos nor MassCore.

#### General

- Pyramix v6.1 MR1 & MR2 projects will not be backwards compatible with the previous Pyramix v6.1.6 release. In order to open such projects in the previous release, please make sure that you perform a Save Special "Save as Version Pyramix V6.1.6".
- Low Memory Condition Warning:

A warning was added to inform users when the system is reaching Low Memory Conditions. In order to save a project under such conditions Pyramix will switch to Save to Disk mode as not enough memory might be available otherwise. This warning was added in order to prevent a Runtime Error on Save.

Note that the Save time in Save to Disk mode in Low Memory Condition might take a longer time since the memory is being dumped to disk in order to allow the users to save their projects. We recommend afterwards to exit and restart Pyramix in order to free all memory.

This Low Memory warning threshold can be adjusted by the user if one wishes it to come earlier or later. With every systems and workflows being different, Merging leave you the ability to adjust when the Warning will show up.

### Procedure:

- Close Pyramix
- Type regedt32 in the run command
- In the registry go to HKEY\_CURRENT\_USER\Software\Merging
  Technologies\Pyramix\Settings\Save to disk threshold (this key will only appear if at least one save was made using that version)
- Default value in Decimal mode has been set to 15
  - The higher the value is set, the earlier the Low Memory warning will come
  - The lower the value is set, the riskier it is for you to encounter a Runtime Error at save (previous Pyramix versions value would have had this value set to 0)

In the near term, Merging expects to significantly further improve (reduce) the memory consumption of Pyramix, especially when confronted with the task of loading enormous libraries, over the coming months. Since this is a rather major re-design, we decided however not to further postpone the release of Pyramix V6.1 for just this very only annoyance.

For the long term, the move of our applications to a 64 bit operating system will provide a very solid platform to accommodate the ever growing project size requirements of some of our users. We are extremely committed to this move but we do need to be clear that it will not be a short term solution, current plans put such a move around 12 months away from today and potentially towards 2011.

- Timeline and Realtime Sampling Rate Conversion: clicks may occur when doing playback or mixdown in a region where 2 overlapping clips reference the same media with different sampling rate than project.
  - Workaround: Convert those medias to the project's sampling rate, prior to using such a workflow.
- Cannot use DiskWrite with Pyramix v6.1: You will need to either re-install Pyramix (maybe run clean up after un-installing Pyramix). Or get a way to Re-install the Gear driver only.
- ADR keyboard is by default disabled. To enable it you must download and run the proper Registry Key. <a href="http://download.merging.com/beta/AssociatedTools/ADRKeyboard.zip">http://download.merging.com/beta/AssociatedTools/ADRKeyboard.zip</a>
- Quickmount generated with V6.1 will not be compatible with previous Pyramix released versions. Remove the Quickmount file if opening a referenced media folder in a previous release.
- Multiple projects opened simultaneously: We do not recommend users to have more than 8 project opened at the same time (due to GDI object limitation).





- Waveforms: Pyramix V6.1 has a new waveform file format that is PK2, such a PK2 waveform file cannot be read in previous Pyramix version and in such a case waveforms will have to be re-generated. On the other side previous waveforms format PK files (Pyramix V6.0 and older) are compatible with Pyramix V6.1. Since Pyramix v6.1MR2 the "Display waveforms while recording" are disabled by default
- The FXRack: Support for delay compensation has not yet been implemented in the FXRack
- Monitoring Panel: Mixer are pre-fader in metering
- The Render Tool will create a temp file for the CEDAR and Nova v0.99 in C:\ Be aware that Merging cannot change the Temp file patch of such third party Render.

### Third Party Plug-ins

- Algorithmix ReNOVAtor for Pyramix: A new version is available with Memory improvements.
   This version will prevent memory related crashes and can be downloaded from www.algorithmix.com
- Cedar: Install issue on certain Vista configurations where you might not see the Cedar plugins after the installation process. The problem is due to erroneous referencing of the license manager utility on a vista machine. Please contact Merging Support or Cedar Support for all details and workaround.
- Cedar: Some toolbar icons might be missing if on a Windows XP system. Workaround: Disable the Skin option in Pyramix>settings>Desktop Layout.
- Altiverb: We recommend users to download the latest version available on the Audio Ease site.
- MP3, AC3 Files and other compressed formats support:
  - Default Windows installation should handle most of the common compressed file formats. In case of problem with the default Widows Installation, Merging has a list of recommended third-party codecs but will not certify any codecs.
     http://forum.merging.com/viewtopic.php?f=18&t=5755
  - Vista users warning: UAC (User Account Control) can be blocking the "Essentials Codec Pack" at startup. If this is the case, you should see once logged into your session at the windows bottom bar a "Windows has blocked some programs" message. You can then unblock it from there or deactivate UAC from the Windows Control Panel.
  - No need to install the previous mp3 beta handler since it is now by default part of the Pyramix installer.

### Hardware

Intel DX58SO Motherboard incompatibility of Windows Vista SP1/SP2 versions:

A conflict has been reported and is under investigation (as of sept 2009) between motherboards using the latest Intel chipset X58 and Mykerinos PCIe cards (such as MYK-X30) under Windows Vista SP1 and/or SP2 versions. Pyramix users with such configurations should remain with the non-SP version of Vista for the time being. Incompatibility of Mykerinos MYK-X50 and X58 chipset based motherboards: a conflict has been reported and is under investigation (as of sept 2009) between motherboards using the latest Intel chipset X58 and Mykerinos PCIe MYK-X50 cards. Pyramix users with MYK-X50 are advised to only use them in X48 chipset based motherboards for the time being. MYK-X30 and Mykerinos PCI cards are not subject to this problem.





# Version Pyramix 6.1MR1

## **Improvements**

- Automation: Erase Points in selection option was added in the track header Automation options (MT3211)
- Automation: Workflow Improvements (MT2921 & MT2517)
  - The Copy/Cut/Paste Automation now works between different Mixers of different projects and between strips that do not have the same buses panner. I.e. Pan automation track can be copied to a stereo track having a Balance. It only works in the usual cases listed below.
    - Pan -> Balance
    - Balance -> Pan
    - LeftRight mono surround panner -> Pan
    - LeftRight mono surround panner -> Balance
    - Pan -> LeftRight mono surround panner
    - Balance -> LeftRight mono surround panner

Limitation: Only in the case of a Mono Strip Pan copied to a Surround stereo panner, will we only carry the left side of the stereo strip's surround panner.

- Added menu option: "Automation > Bus Reassignment on Paste" to enhance the automation workflow between two projects.
  - The Automation > Bus Reassignment left side window, shows the buses automation data of the clipboard.
  - The Automation > Bus Reassignment right side window, shows the available buses of the current mixer.
  - When this On/Off menu is enabled, a window will open to show the automated buses elements under Clipboard and the Destination Mixer Buses.
  - When this On/Off menu is disabled, a window will open only if a Bus in the Clipboard has no Destination Bus.

By default, the "Automation > Bus Reassignment" dialog assigns together the buses which are matching by Bus type.

This dialog allows:

- The Copy an automation track from/to different or similar Buses type of a strip. When type of buses are (i.e. SR1 to ST1)
- The Copy an automation track from/to different type of strips (mono, ms, stereo and GPS).
- Mixer
  - Input Strip Mode Stems entry:

The Strip Usage Type menu (above strip's input connectors) now shows one entry per Stem for Multi-Stems buses. Since effect inserts on Multi-Stems buses are Stem based, this is necessary to guarantee proper delay compensation when dealing with multi-stem Buses.

- Internal Bus display name:
   If an Internal Bus is connected to a bus output, the Bus name will now be appended to the Internal Bus displayed name. (MT3176)
- Panning: More useful pan defaults for channel to surround bus routing (MT2440)
  - Default Panning for Surround on a mono track FRONT/CENTER
  - Default Panning for Surround on a stereo track should be LEFT/L Right/R





- The Delete and Erase Automation functions were rename in the Automation menu and in the track header Automation (A) context menu as:
  - Delete points & Interpolate (Was before "Delete Selected points")
  - Delete points (Was before "Erase Points in Selection")

## **BUG FIXES** (some fixed bugs could be missing from the list)

- MT3251: Fixed. End Record Dubbing crash when without ADR key
- MT3248: Fixed. Cannot set the Delay Compensation to OFF in the Settings page (it reverts to full compensation)
- MT3244: Fixed. Mixer problems when the ASIO buffer size is bigger than 1 TC frame (1920 samples)
- MT3237: Fixed. VST Buffer size value if changed is not kept when re-starting Pyramix
- MT3221: Fixed. Pyramix: Mykerinos TimeCode settings we cannot enable the "Burn in Window" option
- MT3289: Fixed: Mixdown: Crash when doing a Mixdown to MXF file format
- MT3231: Fixed. Un-patching Live in Dubbing Mode doesn't un-patch the Direct Record
- MT3229: Fixed. Some project causes small pauses after a locate or play/stop
- MT3235: Fixed. Crash in Fade Editor if deleting clips in a project.
- MT3226: Fixed. Crash deleting un-mounted clips with library open (out of memory
- MT3183: Fixed. Document library: Cannot trim recorded clips in document library
- MT3230: Fixed. Some project will not relink to Medias unless deleting the \_quickmount or refreshing Media manager.
- MT2354: Fixed. Fade Editor: Memory settings are lost if closing and opening the Fade Editor.
- MT3223: Fixed. Strip Input/Repro connection from the track header above 128th strip was not possible
- MT3222: Fixed. Record does not record in dubbing mode and under some project creation conditions
- MT3190: Fixed. Safe Record: recording is interrupted by any audition command in the fade editor
- MT3119: Fixed. Random crash when going into the Route Mixer page
- MT3156: Fixed. Duplicated media mount / unmount can lead to offline media (no waveform, no sound)
- MT3196: Fixed. Snapshot to library will crash if template-project dates from an older Pyramix version
- MT3153: Fixed. Archive: Give back mount error "Some Media Files referenced by some Clips of your project are currently not accessible"
- MT3145: Fixed. MT Asio Bridge: named Bank 0, 1, 2 etc. they should be named as the inputs MT ASIO 1, 2, 3 etc
- MT3208: Fixed. Media manager: Crash when trimmer is playing back and you switch folder in media browser
- MT3203: Fixed. VST plug-ins do not work for strips placed after a Direct Monitoring strip
- MT3202: Fixed. Fade Editor: when Fade Editor is open, PMX might crash while changing the timeline events
- MT3198: Fixed. Record not aligned if it was started during playback
- MT3177: Fixed. Chase through Sony 9pin results in 1 frame offset
- MT3166: Fixed. AMR utility crashes when converting files (in convert.dll)
- MT3130: Fixed. Record: Pyramix crash when using the "Quiet If Creation Fail" option and enabled dubbing
- MT3197: Fixed. Random crash on record stop
- MT3181: Fixed. Stereo Panning On/Off state issues with Ramses
- MT3138: Fixed. Delay Compensation and effects inserts on multi-stems buses induces a wrong delay compensation computation
- MT3193: Fixed. Chase keyboard shortcut is assigned to the Internal and the Active machine
- MT3182: Fixed. Browsing the Media Manager browser will result in unwanted and incomplete mounted folders.





- MT3158: Fixed. Archive: If the project contains Media in an un-mounted folder, archive will give an "invalid path" error and auto-mount an empty folder
- MT3155: Fixed. Clean Up Media function no longer working in Pyramix v6.1 (From Media Menu)
- MT3154: Fixed. Automation engine frozen after an automation write only if a .pml is open by the .pmx
- MT3149: Fixed. Random Mixer load crash due to a VST plug-in
- MT3148: Fixed. Randomly, Pyramix crashes when opening a project and loading strips
- MT3147: Fixed. Timeline: Adding clip to current selection range using Shift my hang Pyramix
- MT3143: Fixed. Crash on Quick Import
- MT3129: Fixed. Render-Mixdown: Waveforms While Recoding option when using DSD medias into DXD project will show noise in waveforms
- MT3117: Fixed. Automation: Delete automation when track not connected to mixer should autoripple
- MT3110: Fixed. Automation: cannot use delete auto-ripple if timeline tracks are not connected.
- MT2910: Fixed. VS3 effects: Remote initialization problem when several panels
- MT2354: Fixed. Fade Editor: Memory settings are lost if closing and opening the Fade Editor.
- MT2954: Fixed. Digitizing session Auto Stop Record on input levels conditions





### Pyramix V6 Specific Known Issues (Some issues could be missing from this list)

#### MassCore

- Hyperthreading is supported for MultiCore processors only, since Pyramix V6.1
- MassCore is not supported on a Pentium 4 or Pentium D processor, refer to the Installation Guide for the proper supported configuration details.
- We recommend that you do not use more than 65-70% of the Core resources, to avoid intense graphic refresh burst related problems. Three safe core zones have been set. Eventually this will be optimized further.
  - 0% to 65% Green zone (best performance)
  - 65% to 75% Orange zone (moderate risk)
  - 75% to100% Red zone (performance could be at risk if major screen redraws are initiated by the user).
- If the Core indicator blinks (red), this will indicate a drop, only be concerned if the drop occurred during Playback/Mix down or record. To reset the Core drop simply do a Mouse click on the Core indicator, for more information please refer to the appropriate section in the User Manual. VST plug-ins users should consult the VST Core Load information also available in the User Manual.
- External Insert plug-ins: The same input and output cannot be used in the External Insert plug-in and the Mixer at the same time, they are exclusive to either one.
- The MADI 1 daughterboard is not supported in multi-board, neither in Mykerinos nor MassCore.

#### General

- Pyramix v6.1MR1 projects will not be backwards compatible with the previous Pyramix v6.1.6 release. In order to open such projects in the previous release, please make sure that you perform a Save Special "Save as Version Pyramix V6.1.6".
- Low Memory Condition Warning:

A warning was added to inform users when the system is reaching Low Memory Conditions. In order to save a project under such conditions Pyramix will switch to Save to Disk mode as not enough memory might be available otherwise. This warning was added in order to prevent a Runtime Error on Save.

Note that the Save time in Save to Disk mode in Low Memory Condition might take a longer time since the memory is being dumped to disk in order to allow the users to save their projects. We recommend afterwards to exit and restart Pyramix in order to free all memory.

This Low Memory warning threshold can be adjusted by the user if one wishes it to come earlier or later. With every systems and workflows being different, Merging leave you the ability to adjust when the Warning will show up.

### Procedure:

- Close Pyramix
- Type regedt32 in the run command
- In the registry go to HKEY\_CURRENT\_USER\Software\Merging Technologies\Pyramix\Settings\Save to disk threshold (this key will only appear if at least one save was made using that version)
- Default value in Decimal mode has been set to 15
  - The higher the value is set, the earlier the Low Memory warning will come
  - The lower the value is set, the riskier it is for you to encounter a Runtime Error at save (previous Pyramix versions value would have had this value set to 0)

In the near term, Merging expects to significantly further improve (reduce) the memory consumption of Pyramix, especially when confronted with the task of loading enormous libraries, over the coming months. Since this is a rather major re-design, we decided however not to further postpone the release of Pyramix V6.1 for just this very only annoyance.





For the long term, the move of our applications to a 64 bit operating system will provide a very solid platform to accommodate the ever growing project size requirements of some of our users. We are extremely committed to this move but we do need to be clear that it will not be a short term solution, current plans put such a move around 12 months away from today and potentially towards 2011.

- Timeline and Realtime Sampling Rate Conversion: clicks may occur when doing playback or mixdown in a region where 2 overlapping clips reference the same media with different sampling rate than project.
  - Workaround: Convert those medias to the project's sampling rate, prior to using such a workflow.
- Waveforms Display while recording: Some systems configurations will not be adequate for true performance if the Waveforms Display while Recording option is selected in the Pyramix>Playback/Record settings. Mainly due to the Graphic taking too much resources, in such case the stop recording might not be responsive. We recommend in such case that you disable this option in your Pyramix Settings.
- Cannot use DiskWrite with Pyramix v6.1: You will need to either re-install Pyramix (maybe run clean up after un-installing Pyramix). Or get a way to Re-install the Gear driver only.
- ADR keyboard is by default disabled. To enable it you must download and run the proper Registry Key. <a href="http://download.merging.com/beta/AssociatedTools/ADRKeyboard.zip">http://download.merging.com/beta/AssociatedTools/ADRKeyboard.zip</a>
- Quickmount generated with V6.1 will not be compatible with previous Pyramix released versions. Remove the Quickmount file if opening a referenced media folder in a previous release.
- Multiple projects opened simultaneously: We do not recommend users to have more than 8 project opened at the same time (due to GDI object limitation).
- Waveforms: Pyramix V6.1 has a new waveform file format that is PK2, such a PK2 waveform file cannot be read in previous Pyramix version and in such a case waveforms will have to be re-generated. On the other side previous waveforms format PK files (Pyramix V6.0 and older) are compatible with Pyramix V6.1.
- The Render Tool will create a temp file for the CEDAR and Nova v0.99 in C:\ Be aware that Merging cannot change the Temp file patch of such third party Render.

### Third Party Plug-ins

- Algorithmix ReNOVAtor for Pyramix: A new version is available with Memory improvements.
   This version will prevent memory related crashes and can be downloaded from www.algorithmix.com
- Cedar: Install issue on certain Vista configurations where you might not see the Cedar plugins after the installation process. The problem is due to erroneous referencing of the license manager utility on a vista machine. Please contact Merging Support or Cedar Support for all details and workaround.
- Cedar: Some toolbar icons might be missing if on a Windows XP system. Workaround: Disable the Skin option in Pyramix>settings>Desktop Layout.
- Altiverb: We recommend users to download the latest version available on the Audio Ease site
- The Waves plug-ins build v6.0.5.1 are known to maybe cause random crashes when rebuilding the Pyramix Mixer. This issue is being looked at by the Waves team and Merging and is still under investigation.
- MP3, AC3 Files and other compressed formats support:
  - Default Windows installation should handle most of the common compressed file formats. In case of problem with the default Widows Installation, Merging has a list of recommended third-party codecs but will not certify any codecs.
     <a href="http://forum.merging.com/viewtopic.php?f=18&t=5755">http://forum.merging.com/viewtopic.php?f=18&t=5755</a>
  - Vista users warning: UAC (User Account Control) can be blocking the "Essentials Codec Pack" at startup. If this is the case, you should see once logged into your session at the windows bottom bar a "Windows has blocked some programs" message. You can then unblock it from there or deactivate UAC from the Windows Control Panel.





 No need to install the previous mp3 beta handler since it is now by default part of the Pyramix installer.

#### Hardware

Intel DX58SO Motherboard incompatibility of Windows Vista SP1/SP2 versions:

A conflict has been reported and is under investigation (as of sept 2009) between motherboards using the latest Intel chipset X58 and Mykerinos PCIe cards (such as MYK-X30) under Windows Vista SP1 and/or SP2 versions. Pyramix users with such configurations should remain with the non-SP version of Vista for the time being. Incompatibility of Mykerinos MYK-X50 and X58 chipset based motherboards: a conflict has been reported and is under investigation (as of sept 2009) between motherboards using the latest Intel chipset X58 and Mykerinos PCIe MYK-X50 cards. Pyramix users with MYK-X50 are advised to only use them in X48 chipset based motherboards for the time being. MYK-X30 and Mykerinos PCI cards are not subject to this problem.

